

City of Detroit
Department of Recreation Performance Audit
Exhibit 5 – O'Shea Center

Overall Evaluation – Poor Condition

- Grass was too long for effective play.
- Inadequate athletic mill (baseball infield surface material) spread on diamond.
- No protective fencing for the player benches and the backstop was rusted.
- There were no scoreboards.



This baseball field had tall grass and a rough, uneven outfield.

City of Detroit
Department of Recreation Performance Audit
Exhibit 5 – O'Shea Center



This diamond did not have protective fencing around the player benches. Weeds had overtaken the benches.